

PC Engine
(Price List w.e.f.1st May 2026)

#####

| S.N o. | Classification | Article No. | Reference # | Description | Application | List Price |
|--|---|-------------|-------------|--|---|------------|
| Front End Auxilliary Drive (FEAD) - Belt Tensioners | | | | | | |
| 1 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5330081300 | -- | Belt Tensioner Hydraulic ØD = 70, W = 24.5 | Skoda: Octavia 1.9 TDI Volkswagen: Polo Classic 1.9 TDI | 6,712 |
| 2 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340905100 | -- | Belt Tensioner Mechanical ØD = 65, W = 27 | Mahindra 0.9L, 1.5L Diesel - Maxximo, Supro, TUV-300, Quanto | 1,331 |
| 3 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340904100 | -- | Belt Tensioner Mechanical ØD = 65, W = 26 | Ashok Leyland 1.5L TDCR - Dost New | 826 |
| 4 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340907100 | -- | Belt Tensioner Mechanical ØD = 65, W = 26 | Ashok Leyland 1.5L TDCR - Dost Old | 1,009 |
| 5 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340851100 | -- | Belt Tensioner Mechanical ØD = 74, W = 39 | Tata Cummins 6BT BS-III Engine | 1,618 |
| 6 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340848100 | -- | Belt Tensioner Mechanical ØD = 74, W = 34 | Tata Cummins 6CT BS-IV Engine | 3,484 |
| 7 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340059100 | -- | Belt Tensioner Mechanical ØD = 70, W = 24 | Skoda: Laura 1.9 & 2.0 TDI, Supurb 2.0 TDI Automatic Transmission | 3,874 |
| 8 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340151100 | -- | Belt Tensioner Mechanical ØD = 70, W = 24 | Skoda: Laura 1.9 & 2.0 TDI, Supurb 2.0 TDI Volkswagen: Jetta 1.9 & 2.0 TDI, Passat 2.0 TDI (Manual Transmission) | 3,671 |
| 9 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340164100 | -- | Belt Tensioner Mechanical ØD = 70, W = 26 | Audi: A4, A6, Q3, Q5 (2.0 TDI) Skoda: Fabia 1.2 TDI, Laura 2.0 TDI, Rapid 1.6 TDI, Supurb, Yeti (2.0 TDI) Volkswagen: Polo 1.2 & 1.6 TDI, Vento 1.6 TDI, Passat 2.0 TDI | 2,659 |
| 10 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340550100 | F-605991.02 | Belt Tensioner Mechanical ØD = 65, W = 22 | Hyundai 1.1L, 1.4L & 1.6L CRDi (Diesel): Grand i10, Xcent, i20, i20 Elite, i20 Active, Verna, Verna Fluidic, Creta, Elantra, Fluidic Elantra | 1,476 |
| 11 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340636100 | F-603958.01 | Belt Tensioner Mechanical ØD = 65, W = 22 | Tata 1.2L Revotron (Petrol) Engine: Tiago & Tigor | 1,547 |
| 12 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340673100 | -- | Belt Tensioner Mechanical ØD = 66, W = 29 | Tata: 1.3L Quadrajel (Diesel): Bolt, Vista Refresh, Vista Tech, Manza, Manza Club Class, Zest | 1,839 |
| 13 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340674100 | -- | Belt Tensioner Mechanical ØD = 65, W = 26 | Maruti Suzuki 1.3L DDiS (Diesel): Swift, Swift Dzire, Ritz, Ertiga, S-Cross, Vitara Brezza, Baleno, Ignis | 1,029 |
| 14 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340983100 | -- | Belt Tensioner Mechanical ØD = 65, W = 26.5 (Small Tensioner) | Mahindra Nuvisport, Quanto, Scorpio, Scorpio Gataway, TUV 300, Xylo | 1,547 |
| 15 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340927100 | -- | Belt Tensioner Mechanical ØD = 65, W = 26.5 (Big Tensioner) | Mahindra Scorpio, Scorpio Gataway, TUV 300, Xylo | 2,100 |
| 16 | Front End Auxilliary Drive (FEAD) - Belt Tensioners | 5340906100 | -- | Belt Tensioner Mechanical ØD = 65, W = 26.5 | Mahindra 2.2L Diesel mHawk Engine: XUV 500 1st Gen, 2nd Gen & F/L | 1,902 |
| 17 | Front End Auxilliary Drive (FEAD) - Tensioners | 5341014100 | F-621627.01 | Belt Tensioner Hydraulic ØD = 60, W = 32 | Maruti Suzuki- K15B Engine Smart Hybrid Ertiga Gen 2, Ciaz Gen 1 F/, XL6 Gen1, Vitara Breeza F/L, S-Cross Gen 1F/L | 3,235 |
| Idler Pulleys | | | | | | |
| 18 | Front End Auxilliary Drive (FEAD) - Idler Pulleys | 5320507100 | F-234079.07 | Tensioner Pulley (Plastic with Long Spacer) A/C Drive - ØD = 65, W = 21 | Tata 475 IDI / 1.2L & 1.4L MPFi Engine: Indica, Indica EV2, Indica Xeta, Indigo, Indigo CS, Indigo eCs, Indigo Marina, Indigo XL, Indica Vista, Vista Refresh, Vista Tech, Venture. | 456 |
| 19 | Front End Auxilliary Drive (FEAD) - Idler Pulleys | 5320508100 | F-234079.02 | Tensioner Replacement Pulley Flat Alt-PS Drive ØD = 70, W = 24.5 | Tata 475 IDI / 1.2L & 1.4L MPFi Engine: Indica, Indica EV2, Indica Xeta, Indigo, Indigo CS, Indigo eCs, Indigo Marina, Indigo XL, Indica Vista, Vista Refresh, Vista Tech, Venture. | 418 |

PC Engine
(Price List w.e.f.1st May 2026)

#####

| S.N o. | Classification | Article No. | Reference # | Description | Application | List Price |
|--|---|-------------|---------------|---|---|------------|
| 20 | Front End Auxilliary Drive (FEAD) - Idler Pulleys | 5320639100 | F-582028.02 | Idler Pulley (Plastic Plain) ØD = 65, W = 22 | Hyundai 1.1L, 1.4L & 1.6L CRDi (Diesel): Grand i10, Xcent, i20, i20 Elite, i20 Active, Verna, Verna Fluidic, Creta, Elantra, Fluidic Elantra | 446 |
| 21 | Front End Auxilliary Drive (FEAD) - Idler Pulleys | 5320642100 | F-582027 | Idler Pulley (5PK) ØD = 66.4, W = 25.5 | Hyundai 1.1L, 1.4L & 1.6L CRDi (Diesel): Grand i10, Xcent, i20, i20 Elite, i20 Active, Verna, Verna Fluidic, Creta, Elantra, Fluidic Elantra | 713 |
| 22 | Front End Auxilliary Drive (FEAD) - Idler Pulleys | 5320703100 | F-234079.08 | Tensioner Pulley (Plastic with Short Spacer) Alternator Drive - ØD = 65, W = 21 | Tata 1.4L Dicor & CRAIL Engine: Indica, Indica EV2, Indigo, Indigo CS, Indigo eCs, Indigo Marina, Indigo XL, Indica Vista Refresh. | 508 |
| 23 | Front End Auxilliary Drive (FEAD) - Idler Pulleys | 5320831100 | F-558663 | Tensioner Replacement Pulley ØD = 65, W = 26 (6 Rib Belt) | Maruti Suzuki 1.3L DDiS (Diesel): Swift, Swift Dzire, Ritz, Ertiga,S-Cross,Vitara Brezza, Baleno, Ignis | 434 |
| 24 | Front End Auxilliary Drive (FEAD) - Idler Pulleys | 5320847100 | F-571616-0300 | Tensioner Replacement Pulley ØD = 65, W = 29 (7 Rib Belt) | Tata 1.3L Quadrajjet (Diesel): Vista, Manza, Bolt, Zest | 623 |
| 25 | Front End Auxilliary Drive (FEAD) - Idler Pulleys | 5320863100 | F-607522.01 | Idler Pulley (Steel Groove Pulley - 6PK) ØD = 65, W = 29 | Maruti Suzuki 1.3L DDiS Diesel Engine with SHVS: Ertiga, Ciaz 1.3L DDiS Hybrid | 1,343 |
| 23 | Timing Belt Drive (TBD) - Idler Pulleys | 5320881100 | F-618239.01 | Timing Idler Pulley ØD = 60, W = 34 | Tata 1.4L 475 IDI Diesel & 1.2L RT 90PS Petrol Engine: Bolt, In-dica Xeta, Indica V2, Indica Vista, Vista Refresh, Vista Tech, Indigo, Indigo CS, Indigo eCS,Indigo Marina, Venture, Zest | 454 |
| 24 | Timing Belt Drive (TBD) - Idler Pulleys | 5321003100 | -- | FEAD Belt Tensioner Pulley ØD = 75, W = 19.9 (4PK) | Maruti Suzuki 1.0L, 1.2L & 1.4L K-Series Petrol Engine's | 706 |
| 25 | Timing Belt Drive (TBD) - Idler Pulleys | 5320197100 | F-234845.01 | Timing Idler Pulley (Steel) ØD = 28.5, W = 34 | Tata 2.2L Dicor/ Varicor: Safari, Aria, Movus, Safari Storme | 612 |
| 26 | Timing Belt Drive (TBD) - Idler Pulleys | 5320702100 | F-560653.05 | Idler Pulley (Steel-Flat) ØD = 59.7, W = 34 | Tata 1.4L CR4/ CRAIL/ Dicor & 2.2L Dicor Engine: Indica, Indica EV2, Indigo, Indigo CS, Indigo eCs, Indigo Marina, Indigo XL, Safari, Aria, Sumo Grande, Xenon. | 1,618 |
| 27 | Timing Belt Drive (TBD) - Idler Pulleys | 5320883100 | F-578795.02 | Idler Pulley (Steel-Flat with Bolt & Spacer) ØD = 55, W = 30 | Tata 1L, 1.1L Revotorq (Diesel) Engine: Tiago & Tigor | 1,063 |
| 28 | FEAD Pulley | 5321152100 | F-615691.04 | Idler Pulley (Steel) ØD = 65, W = 25 | Mahindra: 1.2L mstallion Petrol Engine: XUV 300, XUV 3X0 | 521 |
| 29 | FEAD Pulley | 5321180100 | F-625028.01 | Idler Pulley (Steel) ØD = 70, W = 30.1 | Maruti Suzuki : (K10B, K12C, K12N, K15C Engine) EECO, ERTIGA, GRAND VITARA, S-PRESSO, SUPER CARRY, XL6 | 757 |
| Over-Running Alternator Pulleys (OAP) | | | | | | |
| 28 | Over-Running Alternator Pulleys (OAP) | 5350232100 | F-585322.01 | Pulley OD: 58 mm Grooves: 7 Alt. Shaft Dia: 17 mm Thread Size: M14x 1.5 Insert Length: 12 mm | TOYOTA FORTUNER INNOVA CRYSTA | 2,217 |
| 29 | Over-Running Alternator Pulleys (OAP) | 5350012100 | F 553470.01 | OAP (Bosch Alternator) Pulley OD (Ø) = 55.9 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 11.1 | Audi: A4 2.0 TDI (Diesel), A4 2.0 TDI Quattro (Diesel), Q3 2.0 TDI Quattro (Diesel), TT 1.8T (Petrol), TT V6 3.2 Quattro (Petrol) Skoda: Fabia 1.2 & 1.4 TDI (Diesel), Laura 1.9 & 2.0 TDI (Diesel), Octavia 1.8 TSI (Petrol), Octavia 1.9 SDI & TDI (Diesel), Octavia 2.0 TDI (Diesel), Rapid 1.6 TDI (Diesel), Superb-II 2.0 TDI (Diesel), Yeti 2.0 TDI (Diesel) Volkswagen: Polo 1.2 & 1.6 TDI, 1.9 SDI & TDI, Jetta 1.4 TSI, Passat 2.0 TDI | 2,038 |

PC Engine
(Price List w.e.f.1st May 2026)

#####

| S.N o. | Classification | Article No. | Reference # | Description | Application | List Price |
|--------|---------------------------------------|-------------|----------------|--|---|------------|
| 30 | Over-Running Alternator Pulleys (OAP) | 5350050100 | F-559320.XXF-2 | OAP (Bosch Alternator) Pulley OD (Ø) = 49.7 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 11.1 | Mercedes Benz: C 220 CDI, Sprinter 3-t bus 316 CDI Force 2.2 TD CRDe TD2200 (Diesel) Engine: Traveller 3350, Traveller Ambulance, Traveller 3050, Traveller 3050 Flat Roof | 1,998 |
| 31 | Over-Running Alternator Pulleys (OAP) | 5350063100 | F 237101.03 | OAP (Valeo Alternator) Pulley OD (Ø) = 54 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 16 | Fiat 1.3 D Multijet / 1.3 JTD Multijet Engine: Fiat 500, Grand Punto, Punto EVO, Punto Pure, Palio, Linea, Avventura | 1,984 |
| 32 | Over-Running Alternator Pulleys (OAP) | 5350077100 | F-225643.13 | OAP (Bosch Alternator) Pulley OD (Ø) = 55.7 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 7.6 | Chevrolet: Captiva 2.0 D & 2.0 D 4WD, Optra 2.0 TDCi | 2,731 |
| 33 | Over-Running Alternator Pulleys (OAP) | 5350102100 | F 550213.08 | OAP (Bosch Alternator) Pulley OD (Ø) = 54.8 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 11.1 (Face - 1st Grv 13.8) | Renault 1.5L dCi (K9K) Diesel Engine: Pulse, Scala, Fluence, Clio, Lodgy, Lodgy Stepway Mahindra 1.4L & 1.6L (K7J/K9M) Petrol Engine: Logan | 2,274 |
| 34 | Over-Running Alternator Pulleys (OAP) | 5350105100 | F-557755.04 | OAP (Valeo Alternator) Pulley OD (Ø) = 55 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 14.4 (Face - 1st Grv 17.45) | Nissan 1.5L dCi (K9K) Diesel Engine: Micra, Micra Active, Sunny, Evalia, Terrano Mahindra 1.5L (K9K) Diesel: Verito, Verito Executive, Verito Vibe | 2,231 |
| 35 | Over-Running Alternator Pulleys (OAP) | 5350110100 | F-233106.05 | OAP (Bosch Alternator) Pulley OD (Ø) = 59.4 Grooves = 6 Alt. Shaft Ød = 15 Thread = M14x1.5 Insert length = 10.1 | Hyundai: Accent Viva 1.5 SOHC-TCI (Diesel) | 2,595 |
| 36 | Over-Running Alternator Pulleys (OAP) | 5350128100 | F-556174.01 | OAP (Bosch Alternator) Pulley OD (Ø) = 58.7 Grooves = 7 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 11.1 | Toyota 2.5L & 3.0L D-4D, 2.4L & 2.8L Diesel, 2.7L Petrol Engine: Innova 1st Gen, Fortuner 1st Gen, Innova Crysta, Fortuner 2nd Gen &, Land Cruiser Prado J120 | 2,186 |
| 37 | Over-Running Alternator Pulleys (OAP) | 5350155100 | F-576346 | OAP (Bosch Alternator) Pulley OD (Ø) = 49.4 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 11.1 | Skoda: Rapid 1.6 (Petrol) & 1.6 TDI (Diesel) Volkswagen: Jetta 1.4 TSI (Petrol), Polo & Vento 1.6 (Petrol) | 1,947 |
| 38 | Over-Running Alternator Pulleys (OAP) | 5350170100 | F-606293 | OAP (Valeo Alternator) Pulley OD (Ø) = 54.71 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 14.4 | Ford 1.5L SOHC DV5 (Diesel): EcoSports, Fiesta | 2,600 |
| 39 | Over-Running Alternator Pulleys (OAP) | 5350173100 | F-567525 | OAP (Denso Alternator) Pulley OD (Ø) = 58 Grooves = 7 Alt. Shaft Ød = 15 Thread = M14x1.5 Insert length = 13 | Toyota 2.5L & 3.0L D-4D, 2.4L & 2.8L Diesel, 2.7L Petrol Engine: Innova 1st Gen, Fortuner 1st Gen, Innova Crysta, Fortuner 2nd Gen &, Land Cruiser Prado J120 | 2,304 |

PC Engine
(Price List w.e.f.1st May 2026)

#####

| S.N o. | Classification | Article No. | Reference # | Description | Application | List Price |
|--------|---------------------------------------|-------------|----------------|---|---|------------|
| 40 | Over-Running Alternator Pulleys (OAP) | 5350187100 | F 236071.08 | OAP (Valeo Alternator) Pulley OD (Ø) = 57 Grooves = 5 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 14.4 | Hyundai 1.1L, 1.2L, 1.4L, & 1.6L DOHC TCI (Diesel): Grand i10, Xcent, i20, i20 Elite, i20 Active, Verna, Fluidic Verna, Creta, Elantra, Fluidic Elantra | 1,994 |
| 41 | Over-Running Alternator Pulleys (OAP) | 5350194100 | F-236591.05 | OAP (Valeo Alternator) Pulley OD (Ø) = 54.2 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 14.4 | Ford 1.4L Duratorque (DV4) TDCi Diesel Engine: Fiesta, Figo | 2,144 |
| 42 | Over-Running Alternator Pulleys (OAP) | 5350201100 | F 558658.01 | OAP (Bosch Alternator) Pulley OD (Ø) = 64.6 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 11.1 | Audi: A6 2.8 FSI (Petrol), 3.2 FSI & FSI Quattro (Petrol), Tata 2.2L Dicor TDiC: Safari Storme, Aria | 2,969 |
| 43 | Over-Running Alternator Pulleys (OAP) | 5350202100 | F-563424.XXF-5 | OAP (Bosch Alternator) Pulley OD (Ø) = 53.7 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 14.4 | Chevrolet: Beat 1.0L Diesel | 2,120 |
| 44 | Over-Running Alternator Pulleys (OAP) | 5350226100 | F-564313.XX | OAP (Valeo Alternator) Pulley OD (Ø) = 55.7 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 11.1 | Chevrolet: Captiva 2.2 D & 2.2 4WD, Cruze 2.0 CDI | 2,389 |
| 45 | Over-Running Alternator Pulleys (OAP) | 5350229100 | F-563515 | OAP (Denso Alternator) Pulley OD (Ø) = 65 Grooves = 7 Alt. Shaft Ød = 17 Thread = M14x1.5 Insert length = 12 | Honda 1.5L i-DTEC Diesel: Amaze, Mobilio, City 6th Gen & 6th Gen F/L, Jazz, BR-V, WR-V | 3,034 |
| 46 | Over-Running Alternator Pulleys (OAP) | 5350243100 | F 560998 | OAP (Valeo Alternator) Pulley OD (Ø) = 54 Grooves = 7 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 16 | Tata: 1.3L Quadrajets (Diesel): Bolt, Vista Refresh, Vista Tech, Manza, Manza Club Class, Zest | 1,673 |
| 47 | Over-Running Alternator Pulleys (OAP) | 5350263100 | F 580053 | OAP (Denso Alternator) Pulley OD (Ø) = 54 Grooves = 6 Alt. Shaft Ød = 17 Thread = M14x1.5 Insert length = 12 | Maruti Suzuki 1.3L DDiS Engine: Swift, Swift Dzire, Ritz, SX4 Hyundai 2.2L DOHC TCI (Diesel): Santa Fe 1st Gen, 2nd Gen, Tucson 2nd Gen Jaguar: XF 2.2 D Range Rover: Evoque 2.2 D 4x4 | 1,652 |
| 48 | Over-Running Alternator Pulleys (OAP) | 5350266100 | F-587370/F-600 | OAP (Valeo Alternator) Pulley OD (Ø) = 58 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 12 | Toyota 1.4L 1NDTV TDCi (Diesel) Engine: Etios, Etios, Cross, Etios Liva | 1,678 |
| 49 | Over-Running Alternator Pulleys (OAP) | 5350305100 | F-608569 | OAP (Bosch Alternator) Pulley OD (Ø) = 55.9 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 11.1 | Ford 1.5L SOHC DV5 (Diesel): EcoSports, Fiesta | 2,361 |
| 50 | Over-Running Alternator Pulleys (OAP) | 5350306100 | F-589431 | OAP (Denso Alternator) Pulley OD (Ø) = 54 Grooves = 6 Alt. Shaft Ød = 15 Thread = M14x1.5 Insert length = 12 | Maruti Suzuki 1.3L DDiS (Diesel): Baleno, Ciaz, Ertiga, Ignis, S-Cross, Swift 2nd Gen, 3rd Gen, Swift Dzire 2nd Gen, 3rd Gen, Vitara Brezza | 1,690 |

PC Engine
(Price List w.e.f.1st May 2026)

#####

| S.N o. | Classification | Article No. | Reference # | Description | Application | List Price |
|---------------------------|---------------------------------------|-------------|-------------|--|---|------------|
| 51 | Over-Running Alternator Pulleys (OAP) | 5350307100 | F-600493 | OAP (Lucas Alternator) Pulley OD (Ø) = 51 Grooves = 4 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 9.7 | Mahindra 0.9L DI (Diesel): Supro, Supro Mini Truck | 1,861 |
| 52 | Over-Running Alternator Pulleys (OAP) | 5350320100 | F-581681 | OAP (Bosch Alternator) Pulley OD (Ø) = 55.87 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 11.1 | Mahindra 2.2L mHawk (Diesel): XUV 500, XUV 500 Refresh | 2,079 |
| 53 | Over-Running Alternator Pulleys (OAP) | 5350321100 | F-610770 | OAP (Bosch Alternator) Pulley OD (Ø) = 53.3 Grooves = 4 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 11.1 | Mahindra 1.5L mHawk (D70): Bolero Power+, TUV-300, Nuvosport, Scorpio Gen3 (Facelift) | 1,367 |
| 54 | Over-Running Alternator Pulleys (OAP) | 5350322100 | F-612939 | OAP (Bosch Alternator) Pulley OD (Ø) = 55.87 Grooves = 5 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 11.1 | Mahindra: KUV-100 1.2L mFalcon G80 (Petrol) | 2,104 |
| 55 | Over-Running Alternator Pulleys (OAP) | 5350323100 | F-587220 | OAP (Lucas Alternator) Pulley OD (Ø) = 55.75 Grooves = 5 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 11.1 | Mahindra: KUV-100 1.2L mFalcon D75 (Diesel), Marazzo 1.5L 4 Cyl (Diesel) | 1,367 |
| 56 | Over-Running Alternator Pulleys (OAP) | 5350324100 | F-607067 | OAP (Valeo Alternator) Pulley OD (Ø) = 55 Grooves = 5 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 11.1 | Tata: Tiago, Tigor, Altroz, Nexon 1.2L Revotron (Petrol) | 1,231 |
| 57 | Over-Running Alternator Pulleys (OAP) | 5350296100 | F-587371 | OAP (Valeo Alternator) Pulley OD (Ø) = 58 Grooves = 6 Alt. Shaft Ød = 17 Thread = M16x1.5 Insert length = 11.1 | Hyundai & Kia: Petrol Engine i20 3RDGEN&F/L, VENUE, CRETA, CARENS, SELTOS, S ONET, TUCSON, VERNA | 1,683 |
| 58 | BDC Mounting Tool Kit | 4001035100 | 0 | BDC Mounting Tool Kit | All Vehicle having alternators with OAP/ OAD Pulley | 3,353 |
| Timing Belt - Kits | | | | | | |
| 59 | Timing Belt - Kits | 5300082100 | -- | Timing Belt Kit No of Belt tooth : 141 | Skoda: Octavia 1.9 TDI & SDI Volkswagen: Golf-4 & Polo Classic 1.9 SDI | 9,270 |
| 60 | Timing Belt - Kits | 5300197100 | -- | Timing Belt Kit No of Belt tooth : 123 | Nissan: Evalia 1.5 dCi (Diesel) Renault: Duster & Fluence 1.5 dCi (Diesel) | 3,724 |
| 61 | Timing Belt - Kits | 5300201100 | -- | Timing Belt Kit No of Belt tooth : 120 | Skoda: Fabia 1.4 TDI, Laura 1.9 & 2.0 TDI Volkswagen: Jetta 1.9 & 2.0 TDI, Passat 2.0 TDI | 9,500 |

PC Engine
(Price List w.e.f.1st May 2026)

#####

| S.N o. | Classification | Article No. | Reference # | Description | Application | List Price |
|--|---|-------------|----------------|--|--|------------|
| 62 | Timing Belt - Kits | 5300239100 | -- | Timing Belt Kit No of Belt tooth : 144 | Ford 1.4L TDCi Engine: Fusion & Ikon | 4,222 |
| 63 | Timing Belt - Kits | 5300550100 | -- | Timing Belt Kit No of Belt tooth : 160 | Audi: A4, Q3, Q5 2.0 TDI Volkswagen: Polo 1.2 & 1.6 TDI, Vento 1.6 TDI Skoda: Fabia 1.2 TDI, Rapid 1.6 TDI, Laura, Superb, Yeti 2.0 TDI | 7,078 |
| 64 | Timing Belt - Kits | 5300572100 | -- | Timing Belt Kit No of Belt tooth : 151 | Chevrolet: Captiva 2.0 D, Cruze 2.0 CDI, Optra 2.0 TDCi | 7,221 |
| 65 | Timing Belt - Kits | 5300578100 | -- | Timing Belt Kit No of Belt tooth : 141 | Ford 1.5L Di-TC (DV5) Diesel Engine: EcoSport, Figo 2nd Gen, Fiesta 2nd Gen, Aspire (old part no. 5300611100) | 4,864 |
| Timing Belt Drive (TBD) - Belt Tensioners | | | | | | |
| 66 | Timing Belt Drive (TBD) - Belt Tensioners | 5310077100 | F-140075.01 | Belt Tensioner Manual ØD = 60, W = 32, with Allen Hole | Tata 475 IDI Engine: IndicaTDi, Xeta, Vista Tdi, Xenon petrol/ CNG, Indigo Marina CS, Tata Ace | 873 |
| 67 | Timing Belt Drive (TBD) - Belt Tensioners | 5310112200 | F-554654 | Belt Tensioner Manual ØD = 42, W = 28 | Daewoo: Matiz, Chevrolet: Spark | 801 |
| 68 | Timing Belt Drive (TBD) - Belt Tensioners | 5310215200 | F-554653 | Belt Tensioner Pulley ØD = 62, W = 28.5 | Toyota 2.5 D-4D&3.0 Engine (2KD-FTV & 1KD - FTV): Innova, Land Cruiser, Prado J120 & J150 | 2,206 |
| 69 | Timing Belt Drive (TBD) - Belt Tensioners | 5310440300 | F-551224F-2326 | Belt Tensioner Mechanical ØD = 67.5, W = 30 | Skoda: Octavia 1.9 TDI | 3,950 |
| 70 | Timing Belt Drive (TBD) - Belt Tensioners | 5310565300 | F-73002 | Belt Tensioner Mechanical ØD = 78.4, W = 35.3 | Skoda : Fabia 1.4 TDI, Laura 1.9 & 2.0 TDI, Superb 2.0 TDI. Volkswagen: Jetta 1.9 & 2.0 TDI, Passat 2.0 TDI | 4,637 |
| 71 | Timing Belt Drive (TBD) - Belt Tensioners | 5310802100 | F-571368 | Belt Tensioner Automatic ØD = 59, W = 32 | Tata 1.4L CR4/ CRAINL/ Dicor & 2.2L Dicor Engine: Indica, Indica EV2, Indigo, Indigo CS, Indigo eCs, Indigo Marina, Indigo XL, Safari, Aria, Sumo Grande, Xenon. | 1,663 |
| 72 | Timing Belt Drive (TBD) - Belt Tensioners | 5310909100 | F-601316 | Belt Tensioner Automatic ØD = 67.7, W = 25.65 | Tata 2.2L Dicor/ Varicor/ BSIV Engine: Safari, Aria, Movus, Safari Storme | 2,980 |
| 73 | Timing Belt Drive (TBD) - Belt Tensioners | 5310925100 | F-618425 | Belt Tensioner Automatic ØD = 59, W = 32 | Tata 1.05L Revotorq Diesel Engine: Tiago & Tigor | 1,852 |
| Timing Chain Drive - Kits | | | | | | |
| 74 | Timing Chain Drive - Kits | 5590014100 | -- | Chain drive Kit (With Sprockets) B8 120 Links | Maruti Suzuki 1.3L DDiS (Diesel): Swift, Swift Dzire, Ritz, Ertiga, S-Cross, Vitara Brezza, Baleno, Ignis Fiat 1.3L Multijet (Diesel): Fiat 500, Palio, Punto, Punto EVO, Grande Punto, Linea, Avventura. Tata 1.3L Quadrajel (Diesel): Vista, Manza, Bolt, Zest | 2,603 |
| 75 | Timing Chain Drive - Kits | 5590019100 | -- | Chain drive Kit (Without Sprockets) B8 120 Links | Maruti Suzuki 1.3L DDiS (Diesel): Swift, Swift Dzire, Ritz, Ertiga, S-Cross, Vitara Brezza, Baleno, Ignis Fiat 1.3L Multijet (Diesel): Fiat 500, Palio, Punto, Punto EVO, Grande Punto, Linea, Avventura. Tata 1.3L Quadrajel (Diesel): Vista, Manza, Bolt, Zest | 2,292 |
| 76 | Timing Chain Drive - Kits | 5590124100 | -- | Chain drive Kit (Without Sprockets) B9 84 Links (Crank-FIP) B9 76 Links (FIP-CAM) | Hyundai 1.1L, 1.4L & 1.6L CRDi (Diesel): Grand i10, Xcent, i20, i20 Elite, i20 Active, Verna, Verna Fluidic, Creta, Elantra, Fluidic Elantra | 9,456 |
| 77 | Timing Chain Drive - Kits | 5590058100 | -- | Chain drive Kit (Without Sprockets) B8 104 Links | Mahindra 0.9L DI & 0.9L C2 CRDe Engine: Maxximo, Maxximo Plus, Supro, Supro Mini Van | 2,600 |
| 78 | Timing Chain Drive - Kits | 5590125100 | -- | Chain drive Kit (With Sprockets) B9 84 Links (Crank-FIP) B9 76 Links (FIP-CAM) | Hyundai 1.1L, 1.4L & 1.6L CRDi (Diesel): Grand i10, Xcent, i20, i20 Elite, i20 Active, Verna, Verna Fluidic, Creta, Elantra, Fluidic Elantra | 14,346 |
| 79 | Timing Chain Drive - Kits | 5590197100 | -- | Chain drive kit | Mahindra 1.5L mHawk Quanto, Bolero Power+, TUV-300, NuvoSport | 2,725 |
| HLA | | | | | | |

PC Engine
(Price List w.e.f.1st May 2026)

#####

| S.N o. | Classification | Article No. | Reference # | Description | Application | List Price |
|-----------|-------------------|-------------|-------------|----------------------------|--|---------------|
| 80 | Valve Train - HLA | 4200086100 | F-46318.37 | HLA ØD = 12, Height = 34.7 | Hyundai 1.2L Kappa (Petrol): i10, i20, i20 Elite, i20 Active, Grand i10, Xcent Ford 1.4 TDCi (Diesel): Figo, Fiesta, Fusion, Classic | 239 |

PC Engine
(Price List w.e.f.1st May 2026)

#####

| S.N o. | Classification | Article No. | Reference # | Description | Application | List Price |
|--------------------------|-----------------------------|-------------|-----------------|---|---|------------|
| 81 | Valve Train - HLA | 4200181100 | F-46318.73 | HLA ØD = 12, Height = 33.4 | Maruti Suzuki 1.3L DDiS (Diesel): Swift, Swift Dzire, Ritz, Ertiga, S-Cross, Vitara Brezza, Baleno, Ignis Fiat 1.3L Multijet (Diesel): Fiat 500, Palio, Punto, Punto EVO, Grande Punto, Linea, Avventura. Tata 1.3L Quadrajel (Diesel): Vista, Manza, Bolt, Zest | 164 |
| 82 | Valve Train - HLA | 4200182100 | F-46318.77 | HLA ØD = 12, Height = 33.4 | Hyundai 1.1L, 1.4L & 1.6L CRDi (Diesel): Grand i10, Xcent, i20, i20 Elite, i20 Active, Verna, Verna Fluidic, Creta, Elantra, Fluidic Elantra | 746 |
| 83 | Valve Train - HLA | 4200250100 | F-46217.18 | HLA ØD = 12, Height = 26.9 | Mahindra 2.5L mDI CRDe (Diesel): Xylo (Gen1, Gen2, Gen3), Genio (DC, SC) | 255 |
| HLA & RFF Set | | | | | | |
| 84 | Valve Train - HLA & RFF Set | 4230099100 | F-446245.13.SL | HLA & RFF Set | Mahindra Petrol Engine: KUV100 & XUV300, XUV 700, Scorpio-N, XUV 3XO Tata Petrol Engine: 1.2L Revotron & Hyperion Petrol Engine Tiago, Tigor, Nexon, Altroz, Punch, Curvv | 420 |
| 85 | Valve Train - HLA & RFF Set | 4230064100 | -- | HLA & RFF Set Engine require: 16 - HLA & 16 RFF | Maruti Suzuki 1.3L DDiS (Diesel): Swift, Swift Dzire, Ritz, Ertiga, S-Cross, Vitara Brezza, Baleno, Ignis Fiat 1.3L Multijet (Diesel): Fiat 500, Palio, Punto, Punto EVO, Grande Punto, Linea, Avventura. Tata 1.3L Quadrajel (Diesel): Vista, Manza, Bolt, Zest | 341 |
| 86 | Valve Train - HLA & RFF Set | 4230078100 | F-446169.13 | HLA & RFF Set Engine require: 12 - HLA & 12 RFF | Tata 1.05L Revortorq, 1.1L Revotorg, 1.4L CR4, CRAIL & Dicor, 1.5L Revotorg, 1.4L Bi-Fuel MPFi (Petrol), 2.2L Dicor, Dicor LET, Varicor (Diesel) Engines: Tiago, Tigor, Indica Indica EV2, Indigo, Indigo Marina, Nexon, Hexa, Aria, Aria LET, Safari Dicor, Safari Storme, Sumo Grande, Movus, Xenon Pick-Up. | 381 |
| 87 | Valve Train - HLA & RFF Set | 4230130100 | F-348339.02 | Hydraulic Lash Adjuster & Roller Finger Follower (HLA-RFF) | Mahindra All Diesel Engine (except 2.5L Diesel engine with rocker arm) | 290 |
| 88 | HLA & RFF | 4230135200 | F-46336.10.ASE | Hydraulic Lash Adjuster & Roller Finger Follower (HLA-RFF) | Hyundai: -1.2L, 1.5L P: i20 Gen3/FL, Creta Gen2/FL, Verna Gen6, Alcazar KIA: - 1.2L, 1.5L P: Seltos, Sonet, Carens | 459 |
| RFF | | | | | | |
| 89 | Valve Train - RFF | 4220064100 | F-446049.05 | RFF Roller ØD = 17 Finger Length = 31.3, Finger width = 18 | Maruti Suzuki 1.3L DDiS (Diesel): Swift, Swift Dzire, Ritz, Ertiga, S-Cross, Vitara Brezza, Baleno Fiat 1.3L Multijet (Diesel): Fiat 500, Palio, Punto, Punto EVO, Grande Punto, Linea, Avventura. Tata 1.3L Quadrajel (Diesel): Vista, Manza, Bolt, Zest | 174 |
| 90 | Valve Train - RFF | 4220229100 | F-446105.10 | RFF Roller ØD = 19 Finger Length = 52.9, Finger width = 18 | Hyundai 1.1L, 1.4L & 1.6L CRDi (Diesel): Grand i10, Xcent, i20, i20 Elite, i20 Active, Verna, Verna Fluidic, Creta, Elantra, Fluidic Elantra | 532 |
| 91 | Valve Train - RFF | 4220235100 | F-446245.18 | RFF Roller ØD = 17 Finger Length = 30.57, Finger width = 15 | Hyundai 1.2L Kappa (Petrol): i10, i20, i20 Elite, i20 Active, Grand i10, Xcent | 252 |
| Rocker Arm | | | | | | |
| 92 | Valve Train - Rocker Arm | 4220284100 | F-446369.04.SV | Rocker Arm: Intake & Exhaust | Tata 3.3L BS-VI Engine - LPK/LPT 912, LPK 1212, LPT 712, LPT 1012, LPT 1112, LPT 1412, LPT 1512, Ultra T.10, T.11, T.12 | 917 |
| 93 | Valve Train - Rocker Arm | 4220285100 | F-446386.06.KIF | Rocker Arm: Intake | Tata 5L BS-VI Engine - LPT 1618, LPT 3521, LPT 1918 TurboTronn, Signa 3521.T, Ultra 1518, Ex 1918.T, 3021.S, T.16 | 1,423 |

PC Engine
(Price List w.e.f.1st May 2026)

#####

| S.No. | Classification | Article No. | Reference # | Description | Application | List Price |
|-------------------|--------------------------|-------------|----------------|---------------------|---|------------|
| 94 | Valve Train - Rocker Arm | 4220286100 | F-446386.07.KI | Rocker Arm: Exhaust | Tata 5L BS-VI Engine - LPT 1618, LPT 3521, LPT 1918 TurboTronn, Signa 3521.T, Ultra 1518, Ex 1918.T, 3021.S, T.16 | 1,437 |
| Water Pump | | | | | | |
| 95 | Water Pump | 5380060100 | -- | Water Pump | SkodaOctavia III1.9L TDI1.9LDiesel | 2,281 |

Disclaimer:

Pricing Information: MRP's revision done for increased affordability for customers in line with Govt directives. Prices are listed in INR and will be effective from 0

Product Availability: Prices and availability of products are subject to change. We reserve the right to correct any errors or omissions, including after an order has

Product Specifications: Product descriptions and applications are provided based on the best available resources; there may be additional applications.

Contact Information: For the most current pricing and product information, please contact the respective sales personnel in your area.